### Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory : Adorn Fashions Ltd.

Address of the Factory : 228/7, Dighirchala, Chandana, Joydebpur, Gazipur

Present Status of the Factory : Under operation.

Structural Assessment Conducted by : BUET

Date of Structural Inspection : 14 January, 2014

Fire Assessment Conducted by :

Date of Fire Inspection :

Electrical Assessment Conducted by :

Date of Electrical Inspection :

BGMEA Membership No. : 5038

#### **BASIC INFORMATION:**

The present garment factory is housed in a Six-story reinforced concrete building. The reinforced concrete building is a RC frame with flat plate flooring system. The following information was noted:

i. Building Usage Type : Commercial Building.

ii. Structural System : RC columns with flat plate floors.

iii. Floor System : Flat plate.

iv. Floor Area : Approx. 6000- 7200 sft/floor (used by Bulbul Knitting)

v. No. of Stories : 6 (Six)

vi. Construction Year : 2008-2009 (as reported)

vii. Foundation Type : Individual footing (3.05m×3.05m, Reinforcement: 20mm

@5inch c/c both way)

viii. Design Drawings : Reinforced concrete building design drawing is partially

available (only one sheet). Consultant: Planning and Engineering Consultants, Jorpukur, Joydebpur, Gazipur.

ix. Soil Investigation Report : Available (conducted in March 2008 by The National Soil

Engineers, 186/A West Kafrul, Old Taltola, Sher-e-Bangla

Nagar, Dhaka-1207)

x. Construction Materials : Not Available (Assumed brick chips for RC and 40 Grade

reinforcement).

xi. Generator : Generator is located at the GF of building.

#### RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

Short Term (Immediate) : The factory owner has to prepare and submit the load plan for all

floors within three weeks for approval

Mid Term (6-weeks) : N/A

Long Term (6-months) : A Detail Engineering Assessment (DEA) has to be completed.

Necessary remediation's after completion of DEA.

Adorn Fashions Ltd. Last update on Page 1

# Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

The recommendations for **Fire & Electrical Safety** corrective action are:

## (A): Recommendations for Fire Safety Corrective Actions:

Immediate	
(the factory should not continue to be occupied until these non-conformities have been rectified):	
Short Term	
(Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity	
Mid Term	
(The remedial works indicated must be carried out within a period of 6 weeks)	
Long Term	
(The remedial works indicated must be carried out within a period of 6 months)	

### (B): Recommendations for Electrical Safety Corrective Actions:

Immediate	
(the factory should not continue to be	
occupied until these non-conformities	
have been rectified):	
Short Term	
(Actions that must be incorporated into	
a Fire Safety Management Plan	
immediately (a week) and should be a	
regular activity	
,	
Mid Term	
(The remedial works indicated must be	
carried out within a period of 6 weeks)	
Long Term	
Long Term	
(The remedial works indicated must be	
carried out within a period of 6	
months)	
, and the second	

Adorn Fashions Ltd. Last update on Page 2