

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

---

Name of the Factory	: Apace Ltd.
Address of the Factory	: 436/457, Chatterwari Road, Gazi Shah Lane, Dev Pahar, Chittagong, Bangladesh.
Present Status of the Factory	: Under Operation
Structural Assessment Conducted by	: VERITAS Engineering & Consultant
Date of Structural Inspection	: 2015-10-03
Fire Assessment Conducted by	: VERITAS Engineering & Consultant
Date of Fire Inspection	: 2015-10-03
Electrical Assessment Conducted by	: VERITAS Engineering & Consultant
Date of Electrical Inspection	: 2015-10-03
BGMEA Membership No.	: 3309

**BASIC INFORMATION:** The present garment factory is a four storied RCC beam column frame structure. The following general information was noted:

i. Building Usage Type	: Garment factory
ii. Structural System	: RCC beam column.
iii. Floor System	: RCC Beam slab.
iv. Floor Area	: 12000 sft.
v. No. of Stories	: 4-stories
vi. Construction Year	: 1995-96.
vii. Foundation Type	: Isolated column footing.
viii. Design Drawings	: Available documents: structural design drawing, approval plan, Soil test report and machine layout plan. Not available: architectural design drawing, floor load plan and Material test report.
ix. Soil Investigation Report	: Available
x. construction Materials	: Brick Chips (column).
xi. Generator	: Ground floor.

**RECOMMENDATIONS FOR CORRECTIVE ACTION: Corrective action for structure are,**

Short Term (Immediate)	: N/A
Mid Term (6-weeks)	: 1. Factory Engineer to review design, loads and columns stresses in area identified above.
Long Term (6-months)	: 1. Engineer to inspect whether waterproofing material is applied or where it can be maintained. For both durability and serviceability, waterproofing on the roof slab is recommended. Moreover the roof slab drainage system should be investigated.

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

---

The recommendations for **Fire & Electrical Safety** corrective action are:

**(A): Recommendations for Fire Safety corrective actions:**

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<p>N/A</p>
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity</i></p>	<ul style="list-style-type: none"> <li>• Factory needs to conduct fire drill quarterly (4 times a year) under the fire safety plan and needs to kept the written record of such drills for at least 3 years for the inspection of fire brigade whenever called for.</li> <li>• Factory need to have proper testing plan &amp; record of fire safety equipment.</li> <li>• Factory needs to have marked aisles in all working floor according to 0.9m for one side seat and 1.0m for both side seat.</li> <li>• Factory need to reduce worker or occupant load from 3rd floor.</li> <li>• Lights in storage area needed to be installed with protective covers and conduits.</li> <li>• Combustibles are to be managed with good housekeeping. Storage facilities with no air-conditioning duct shall be minimum 2.9 m and when used as a storage facility there shall be a minimum clearance of one third the floor height from the ceiling to the top of the storage stack.</li> <li>• All required means of exit or exit access in buildings or areas requiring more than one exit shall be signposted. The signs shall be clearly visible at all times, where necessary supplemented by directional signs.</li> </ul>
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<ul style="list-style-type: none"> <li>• Factory needs to have as built drawing with floor machine layout showing means of escape with proper dimension.</li> <li>• Fire license needs to be updated for full occupied area.</li> <li>• Fire manager/Director need to have safety training from proper authority &amp; worker of the factory should as far as possible be trained for use fire extinguisher.</li> <li>• All the exit doors need to be replaced by side swinging so that un-lockable doors can be opened easily in the direction of evacuation without the use of a key.</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<ul style="list-style-type: none"> <li>• Factory needs to provide handrail on both sides of all the stairways.</li> <li>• Factory needs to be installed with adequate illuminated emergency lighting in floors, exits &amp; stairs. (Escape route).</li> <li>• Emergency back-up power needs to be connected for critical fire safety system and not less than 30 minutes in case of failure of power supply.</li> </ul>
<p>Long Term</p> <p>(The remedial works indicated must be carried out within a period of 6 months)</p>	<ul style="list-style-type: none"> <li>• Fire department pre-plan needs to be developed.</li> <li>• Final exit route-1(Stair-1 route) need to be protected (2 hours rated construction with 1.5 hours rated door) at each floor level entrance including ground floor and need to be protected from the generator at ground floor by 4 hours rated construction with 2 hours rated door/opening, also need to have the protected escape route till to reach safe refuse area.</li> <li>• Final exit route-2(Stair-2 route) need to be protected (2 hours rated construction with 1.5 hours rated door) at each floor level entrance including ground floor and need to have the protected escape route till to reach safe refuse area.</li> <li>• Storage area need to be protected with 2 hours rated construction &amp; 1.5 hours rated opening or doors.</li> <li>• Boiler: Boiler room needs to be protected with 4 hours rated construction &amp; 2 hours rated opening / door from the working floor (Finishing &amp; Iron section) at 1st floor of the building.</li> <li>• Generator: Generator room need to be protected with 4 hours rated construction &amp; 2 hours rated opening / door at ground floor respectively.</li> <li>• All the stairs need to be protected with fire and smoke resistant enclosures and opening (2 hours rated enclosure and 1.5 hours rated door) and provide a protected route from all though the stairway to the final exits.</li> <li>• Factory need to install centralized and automatic fire detection &amp; alarm system on all occupied floors, including other tenanted floors of the building as per NTPA Guideline.</li> <li>• The factory need to install manually operated electrical fire alarm system and automatic fire alarm system with single or multiple call boxes on all occupied floors, including other tenanted floors of the building.</li> <li>• Factory needs to install control panel for centralized automatic smoke detection &amp; fire alarm system according to NTPA Guideline</li> <li>• Factory needs to install proper standpipe system with having at least</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>100 mm dia of riser.</p> <ul style="list-style-type: none"> <li>• Factory needs to install 1 hose per 1000 m<sup>2</sup> and the minimum hose diameter is 38 mm, or 1.5" preferably fabric hose with variable nozzle.</li> <li>• Factory needs to ensure the minimum pressure for standpipes supplying a 50mm or larger hose shall be at least 300 Kpa. For standpipe supplying first aid hose (38mm nominal) may have a minimum pressure of 200 Kpa.</li> <li>• Factory needs to be installed with Siamese connection for to the standpipe system located outside the building and accessible to the fire department connection.</li> <li>• Factory needs to have dedicated fire pump with backup power system &amp; sufficient capacity for achieve required pressure in the remote place of the factory.</li> <li>• Factory need to have sufficient water storage capacity to get adequate pressure to feed fire-fighting equipment and at least <math>1900 \times 75 = 142500</math> liters water storage tank.</li> </ul>
--	---

### **(B): Recommendations for Electrical Safety corrective actions:**

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<ul style="list-style-type: none"> <li>• Find out the cause (improper cable/over current selection, over loading, improper lug, improper cable joints, rusted connection, insulation damage, multiple cables at single point, ) of overheating (&gt; ambient+ 400C) and take proper action.</li> </ul>
<p>Short Term (Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity)</p>	<ul style="list-style-type: none"> <li>• Provide two separate and distinct connections of earthing for the generator.</li> <li>• Ensure all distribution boards (including panel door) are earthed properly.</li> <li>• Clean interior components from dust and debris and seal all openings within the enclosure to prevent dust and debris from entering.</li> <li>• Provide provision for inspection of all earthing system and ensure inspection is being completed and documented.</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<ul style="list-style-type: none"> <li>• Install appropriate number and type of safety signage and fire-fighting equipment at generator room. Also ensure graded rubber mats are provided in front of all distribution boards.</li> <li>• Provide Instruction board for first aid and artificial respiration in the generator room.</li> <li>• Ensure in the generator room has adequate illumination level as per standard.</li> <li>• Provide dedicated &amp; adequate size of earthing with proper identification for each circuit from the earth bus-bar of distribution boards and ensure continuous earth path is back to main building intake.</li> <li>• Rewire to ensure each incoming supply to an MCB has a dedicated supply from busbar.</li> <li>• Avoid the use of multiple cables on outgoing side of MCB's.</li> <li>• Replace wooden box with metal clad construction for mounting the switch control.</li> <li>• Ensure all electrical cables are sized according to capacity of circuit breakers.</li> <li>• Ensure cable joints are made in respect of conductivity, insulation and mechanical strength.</li> <li>• Connect all metal in the building to the building earthing system.</li> <li>• Find out the cause (improper cable/over current selection, over loading, improper lug, improper cable joints, rusted connection, insulation damage, multiple cables at single point, ) of overheating { ambient+( 200C-400C)} and take proper action.</li> </ul>
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<ul style="list-style-type: none"> <li>• Develop an electrical layout diagram and an as-built single line diagram detailing key components and capacity of the electrical system.</li> <li>• Establish a periodical Insulation and earth Resistance Measurement Program and record the related testing data.</li> <li>• Inspect electrical panel boards on an annual basis.</li> <li>• Ensure overhead service connections to the building are led via adequate size and type of service masts.</li> <li>• Ensure distribution boards have no opening and all live internal components are concealed properly.</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

---

	<ul style="list-style-type: none"><li>• Provide dedicated &amp; adequate size of neutral with proper identification for each circuit.</li><li>• Ensure each distribution board is provided with a circuit list and means of identification is provided as per list.</li><li>• Provide adequate covers on cable channels.</li><li>• Provide proper cable terminator/connector for stranded conductors at its point of termination.</li><li>• Install separate distribution boards for lighting and power circuits.</li><li>• Install lightning protection system on the building.</li></ul>
--	--