

## **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

---

Name of the Factory	: SONNET TEXTILE INDUSTRIES LTD.
Address of the Factory	: Mazid tower, 807/859, Barik Mia high school lane, Goshaldanga, Bander, Chittagong
Present Status of the Factory	: Under operation.
Structural Assessment Conducted by	: ACCORD
Date of Structural Inspection	:
Fire Assessment Conducted by	: TUV
Date of Fire Inspection	: 13 December, 2015
Electrical Assessment Conducted by	: TUV
Date of Electrical Inspection	: 13 December, 2015
BGMEA Membership No.	: 1528

### **BASIC INFORMATION:**

The assessed factory building is 7 - Story R.C.C structure. The frame system of the building is beam-column frame all through the structure. The following information was noted:

- i. Building Usage Type : Garment Factory.
- ii. Structural System : RCC beam column system.
- iii. Floor System : RCC Beam slab.
- iv. Floor Area :
- v. No. of Stories : 7 - Story
- vi. Construction Year :
- vii. Foundation Type :
- viii. Design Drawings :
- ix. Soil Investigation Report :
- x. Construction Materials :
- xi. Generator :

### **RECOMMENDATIONS FOR CORRECTIVE ACTION:**

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

- |                        |   |
|------------------------|---|
| Short Term (Immediate) | : |
| Mid Term (6-weeks)     | : |
| Long Term (6-months)   | : |

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

The recommendations for **Fire & Electrical Safety** corrective action are:

**(A): Recommendations for Fire Safety Corrective Actions:**

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<p>N/A</p>
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity</i></p>	<ul style="list-style-type: none"> <li><input type="checkbox"/> Provide aisle marking with arrow guiding and exit signage on all Evacuation pathways or provided with overhead signage fixed at ceiling level.</li> <li>- Illuminated exit sign should be posted above the exit door,</li> <li>- It should be clearly visible at all time,</li> <li>- Provide directional signs wherever necessary.</li> <li>- All exit doors should be clearly marked for easy identification.</li> <li>-Signage should be uniform</li> <li><input type="checkbox"/> The first aid hose and standpipe performance should be checked periodically and properly tagged.</li> </ul>
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<ul style="list-style-type: none"> <li><input type="checkbox"/> Replace all existing exit doors on evacuation routes, exit doors with side hinged type door, which swing outward and in the direction of travel. Swinging of the door should not constrict the width of the corridor / passage below 0.9 meter.</li> <li><input type="checkbox"/> Remove all locking device from all egress door. All exit doors should be open-able from the side they serve without the use of a key.</li> <li><input type="checkbox"/> Provide handrails on both side of each stairway with height of 0.9m measured from the nose of stair to the top of the handrail.</li> <li><input type="checkbox"/> Doors in stair should be outward opening, side-swing, self closing, non-lockable 2 hours fire rated doors in all stair way encloses.(Also needs to cover the floors occupied by other tenants)</li> <li><input type="checkbox"/> Prepare design for installation of fire rating smoke proof enclosure. 2 hours fire rating doors for exit should not be less than that of 4 hours fire resistance rating of the walls of the smoke proof fire rated entry lobby(Also needs to cover the floors occupied by other tenants).</li> <li><input type="checkbox"/> Prepare proper plan and design for 4 hours fire rated barriers with 2 hours fire rated doors at ground floor electrical substation and generator room, which located at the adjacent to south side final exit</li> <li><input type="checkbox"/> Prepare proper plan and design for 2 hrs fire rated barrier with 1.5 hrs fire rated door for storage area at ground floor.</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>Provide 1.5 fire rated door at 1st floor bonded store</p> <ul style="list-style-type: none"> <li><input type="checkbox"/> Prepare proper plan and design for 4 hours fire rated barriers with 2 hours fire rated door at 2nd floor boiler room, which located at the adjacent to finishing section</li> <li><input type="checkbox"/> The egress paths should be illuminated with emergency lighting with power back-up supply &amp; illumination should be a minimum of 10 lux for all corridors &amp; exit doors. Aisles should be provided with a minimum 2 lux.</li> <li><input type="checkbox"/> Produce design and plan for automatic detection system with automatic fire alarm and control panel.(Also needs to cover the floors occupied by other tenants)</li> <li><input type="checkbox"/> Provide adequate nos. of smoke detectors to cover the whole factory building.</li> <li><input type="checkbox"/> Prepare proper design and plan for dedicated fire pump with alternate backup power supply.</li> <li><input type="checkbox"/> Replace existing 1 inch hose pipe with 1.5 inch hose pipe to meet the requirement of RMG guideline.</li> <li><input type="checkbox"/> Prepare plan and design for dedicated water storage tank for firefighting operation as per RMG guideline.</li> <li><input type="checkbox"/> Prepare proper design and plan for fire lifts equipped with approved intercommunication (including two way voice communications) with the fire command station or control room on the ground floor lobby of the building.</li> <li><input type="checkbox"/> Complete full design and plan for providing fire command station equipped with detailed floor plans along with clearly demarcated locations of fire detection and fighting devices and through the panel board able to detect fire alarm from any floor.</li> </ul>
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<ul style="list-style-type: none"> <li><input type="checkbox"/> Install smoke proof fire rated entry lobby at emergency stairways to separate from the area of incidence (Also needs to cover the floors occupied by other tenants).</li> <li><input type="checkbox"/> Provide 4 hours fire rated barriers with 2 hours fire rated doors at ground floor electrical substation and generator room, which located at the adjacent to south side final exit</li> <li><input type="checkbox"/> Provide 2 hrs fire rated barrier with 1.5 hrs fire rated door for storage area at GF.</li> <li><input type="checkbox"/> Provide 4 hours fire rated barriers with 2 hours fire rated door at 2nd floor boiler room, which located at the adjacent to finishing section</li> <li><input type="checkbox"/> Install automatic detection system with automatic fire alarm and control panel.(Also needs to cover the floors occupied by other tenants)</li> <li><input type="checkbox"/> Install dedicated fire pump with alternate backup power supply.</li> <li><input type="checkbox"/> Stand pipe supplying first aid hose should have minimum</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>pressure of 200 KPa.</p> <ul style="list-style-type: none"> <li><input type="checkbox"/> Provide dedicated storage tank for firefighting operation</li> <li><input type="checkbox"/> Install fire lifts equipped with approved intercommunication (including two way voice communications) with the fire command station or control room on the ground floor lobby of the building.</li> <li><input type="checkbox"/> Provide fire command station equipped with detailed floor plans along with clearly demarcated locations of fire detection and fighting devices and through the panel board able to detect fire alarm from any floor.</li> </ul>
--	--

### **(B): Recommendations for Electrical Safety Corrective Actions:**

<p><b>Immediate</b></p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	N/A
<p><b>Short Term</b></p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity</i></p>	<ul style="list-style-type: none"> <li><input type="checkbox"/> All strands cables at exposed ends should be properly soldered / crimped and insulated.</li> </ul>
<p><b>Mid Term</b></p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<ul style="list-style-type: none"> <li><input type="checkbox"/> Refill the silica gel. Ensure that accessories of transformers like breathers, vent pipe, buchholz relay, silica gel must be in order at substation.</li> <li><input type="checkbox"/> Install smoke detection and provide firefighting equipment in the substation and generator room.</li> <li><input type="checkbox"/> Provide and maintain clear and legible identifications numbers &amp; names on all incoming and outgoing circuits of HT / LT panels.</li> <li><input type="checkbox"/> Provide cable connections with properly soldered / welded lugs at (LT/MDB/DB/SDB)'s. Ensure that all the electrical connections are properly secured with lugs.</li> <li><input type="checkbox"/> Avoid bunching of cable at bus bar, use individual circuit and over current device for every incoming and outgoing circuit at the distribution boards.</li> <li><input type="checkbox"/> Provide cable joints of porcelain / PVC connectors with PIB tape wound around before placing the cable in the box.</li> <li><input type="checkbox"/> Provide proper separate earthing/grounding to generator. Ensure that generator body frame to have two separate and distinct connections to the earth / ground.</li> </ul>

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

---

<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<ul style="list-style-type: none"><li><input type="checkbox"/> Area of substation / transformer to meet requirements of Table 4.3 of RMG Guideline; the area should be 45m<sup>2</sup>, or relocate the substation/ transformer room.</li><li><input type="checkbox"/> Provide 4 hour fire rated walls all around the generator room on ground level.</li><li><input type="checkbox"/> For buildings &gt; 20m high, provide at least one vertical shaft of 200 x 400 mm for every 1500 sq.m. floor area.</li><li><input type="checkbox"/> 1. Provide the ECC to meet minimum cross-sectional area as per table 4.5.</li><li>2. Ensure that connections between conductors / equipment are provided to durable electrical continuity and adequate mechanical strength and protection.</li><li>3. The continuous earth connection is provided back to the main intake supply earth.</li><li><input type="checkbox"/> Provide adequate protection against lightning depending on the probability of a strike and acceptable risk levels at roof top of building.</li></ul>
---	---