

## **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

---

Name of the Factory	: Dastagir Knitwears (Pvt.) Ltd
Address of the Factory	: 25-26, Postagola I/A, Postagola, Dhaka
Present Status of the Factory	: Not in Operational
Structural Assessment Conducted by	: TÜV SÜD Bangladesh (Pvt.) Ltd
Date of Structural Inspection	: 2015-10-25
Fire Assessment Conducted by	: TÜV SÜD Bangladesh (Pvt.) Ltd.
Date of Fire Inspection	: 2015-10-25
Electrical Assessment Conducted by	: TÜV SÜD Bangladesh (Pvt.) Ltd.
Date of Electrical Inspection	: 2015-10-25
BGMEA Membership No.	: 5006

### **BASIC INFORMATION:**

- |                               |  |
|-------------------------------|--|
| i. Building Usage Type        | : Garments Factory.                      |
| ii. Structural System         | : RCC Frame Building.                    |
| iii. Floor System             | : Beam-Slab System.                      |
| iv. Floor Area                | : Not measured.                          |
| v. No. of Stories             | : GF+ 3 floors, (4 Storey), No Basement. |
| vi. Construction Year         | : Not known.                             |
| vii. Foundation Type          | : Not verified.                          |
| viii. Design Drawings         | : Not verified.                          |
| ix. Soil Investigation Report | : Not verified.                          |
| x. construction Materials     | : Not verified.                          |
| xi. Generator                 | : Not verified.                          |

**RECOMMENDATIONS FOR CORRECTIVE ACTION:** For Structural corrective actions are,  
Factory could not be assessed.

The recommendations for **Fire & Electrical Safety** corrective action are:

**(A): Recommendations for Fire Safety corrective actions:**

Factory could not be assessed.

So, the level of compliance of the factory could not be determined for any of the 67 checkpoints as per the NTPA guidelines.

## Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

---

*(B): Recommendations for Electrical Safety corrective actions:*

Factory could not be assessed.