

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory	: Wise Apparels Ltd.
Address of the Factory	: 78, Shah Kabir Majar Road, Bepari Para, Uttar Khan, Uttara, Dhaka.
Present Status of the Factory	: Non Operational
Structural Assessment Conducted by	: TÜV SÜD Bangladesh (Pvt.) Ltd.
Date of Structural Inspection	: 2015-09-03
Fire Assessment Conducted by	: TÜV SÜD Bangladesh (Pvt.) Ltd.
Date of Fire Inspection	: 2015-09-03
Electrical Assessment Conducted by	: TÜV SÜD Bangladesh (Pvt.) Ltd.
Date of Electrical Inspection	: 2015-09-03
BGMEA Membership No.	: 4902

BASIC INFORMATION:

i. Building Usage Type	: Garment Factory
ii. Structural System	: Steel truss structure supported by RCC columns and brick walls.
iii. Floor System	: Ground floor
iv. Floor Area	: Not measured
v. No. of Stories	: Single storey, No Basement.
vi. Construction Year	: Not known
vii. Foundation Type	: Not verified
viii. Design Drawings	: Not verified
ix. Soil Investigation Report	: Not verified
x. construction Materials	: Not verified
xi. Generator	: Not verified

RECOMMENDATIONS FOR CORRECTIVE ACTION: Factory could not be assessed for structure.

The recommendations for **Fire & Electrical Safety** corrective action are:

(A): Recommendations for Fire Safety corrective actions:

As the factory was not operational in this building. So, the level of compliance of the factory could not be determined for any of the 67 checkpoints as per the NTPA guidelines.

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

(B): Recommendations for Electrical Safety corrective actions:

Factory could not be assessed